

Table of AD-Notes and Technical Notes

**ALEXANDER SCHLEICHER**

GMBH & CO

Segelflugzeugbau  
D-36163 Poppenhausen

Type: **ASW 24 E**

Data Sheet No.: **859**

Sheet: **1 of 1**

LBA-License No. 1-B1

TN-No	LBA-AD-No. Issue Date	TN Issue Date	Version & Serial no.s affected	Subject	Compliance	Inspection Ref.
<b>1</b>		<b>26.03.89</b> LBA- app.:05.03.90	all ASW 24, ASW 24 E and ASW 24 TOP for registration in the Netherlands	Some structural modification are necessary for the Netherlands (only in german language)	only for Export to the Netherlands	
<b>2</b>	<b>92-8</b> 17.02.92	<b>07.11.91</b> LBA-app.:18.12.91	all ASW 24 E as of 24801 until 24847 as of 24848 serial standard	A) Securing of the screws at the engine support bracket. B) Replacemant of the lower support bracket of the gas spring near the screw jack. C) Supplement to the Maintenance Manual.	ad A) and B): prior to the next take-off ad A) until C): on the occasion of the next annual C. of. A. inspection, but before or on <b>March 31, 1992</b> , at the latest	
<b>3</b>	<b>RAI- approved</b> 03.03.92	<b>03.03.92</b>	all ASW 24 E for Export Italy	Flight Manual Revision	only for Export to Italy	
<b>4</b>		<b>09.09.92</b> LBA-app.:20.10.92	all ASW 24 E	Modification for optional operation with/without 0,3 m high winglets	none, optional mod only	
<b>5</b>		<b>05.01.95</b> LBA-app.:09.01.95	all ASW 24 E	Improvement of the product by modification of the wing leading edge section. Optional retrofit mod to the outboard wing leading edge	None, optional retrofit mod or optional when building new pair of wings for major repairs	
<b>6</b>		<b>28.06.99</b> LBA-appr.: 14.03.00	all ASW 24 E	Nose bolt with O-Ring for horizontal tail (provisional only in german issue)	none, optional on customer's request	